


Line Length 50.02 5.52 1.19 34.76	Table Direction \$72°35'06"E \$18°11'01"W \$71°54'57"E \$18°10'24"W
50.02 5.52 1.19	S72°35'06"E S18°11'01"W S71°54'57"E
5.52	S18°11'01"W S71°54'57"E
1.19	S71°54'57"E
34.76	C18°10'24"W
	3101024 W
40.15	N17°26'50"E
50.14	S72°27'17"E
39.78	S17°32'43"W
150.14	N72°27'17"W
39.78	N17°32'22"E
	39.78



VICINITY MAP NOT TO SCALE

1. THIS SURVEY WAS PREPARED WITHOUT THE BENEFIT OF A COMMITMENT FOR TITLE INSURANCE, WITH REGARD TO ANY RECORDED EASEMENTS, RIGHTS-OF-WAY OR SETBACKS AFFECTING THE SURVEYED PROPERTY. NO ADDITIONAL RESEARCH REGARDING THE EXISTENCE OF EASEMENTS, RESTRICTIONS, OR OTHER MATTERS OF RECORD HAS BEEN PERFORMED BY THE SURVEYOR.

2. THE COORDINATES AND BEARINGS SHOWN HEREON ARE TEXAS SOUTH CENTRAL ZONE NO. 4204 STATE PLANE GRID COORDINATES (NAD83) AND MAY BE BROUGHT TO SURFACE BY APPLYING THE FOLLOWING COMBINED SCALE: 0.99988954428.

3. ACCORDING TO THE FEDERAL EMERGENCY MANAGEMENT AGENCY (FEMA) FLOOD INSURANCE RATE MAP No. 48201C0880M, REVISED DATE OF JANUARY 6, 2017, THE SURVEYED PROPERTY LIES WITHIN ZONE "X" (UNSHADED), AREAS DETERMINED TO BE OUTSIDE THE 0.2% ANNUAL CHANCE FLOODPLAIN.

4. METES AND BOUNDS DESCRIPTIONS OF THE SURVEYED PROPERTIES WAS PREPARED IN CONJUNCTION WITH AND ACCOMPANIES THIS SURVEY.

SYMBOLS

= FOUND 5/8-INCH IRON ROD (UNLESS OTHERWISE NOTED) SET 5/8-INCH IRON ROD WITH MILLER SURVEY GROUP CAP (UNLESS OTHERWISE NOTED)

■ = A.C. PAD

■ BLOW OFF VALVE

= BOLLARD

= BUSH

CABLE BOX

CABLE MARKER

 $co_0 = CLEAN-OUT$

= CURB INLET

= E-INLET

E = ELECTRIC BOX

= ELECTRIC MANHOLE = FIRE DEPARTMENT CONNECTION

= FLAG POLE

= FLUSH VALVE

■ GAS METER

© = GREASE TRAP = GUY ANCHOR

= HANDICAPPED PARKING SPACE

= IRRIGATION CONTROL VALVE

J = JUNCTION BOX ★ = LIGHT STANDARD

PM = PIPELINE MARKER

= POWER POLE

= POWER POLE W/LIGHT

S = SAMPLE WELL SANITARY MANHOLE

= SERVICE POLE

_O = SIGN

⇔ = SPRINKLER HEAD

= STORM MANHOLE

 TELEPHONE MANHOLE

= TRAFFIC SIGNAL CONTROL BOX

(= TRAFFIC SIGNAL POLE

WATER METER ■ WATER VALVE

I CERTIFY THAT THE HEREIN PLAT AND THE SURVEY ON WHICH IT WAS BASED MEET THE MINIMUM REQUIREMENTS OF A CATEGORY 1A, CONDITION II SURVEY, AS DESCRIBED IN THE TEXAS SOCIETY OF PROFESSIONAL LAND SURVEYORS — MANUAL OF PRACTICE. THE FIELD WORK WAS COMPLETED ON JANUARY 21, 2020.

DATED THIS THE 3RD DAY OF SEPTEMBER, 2020

TEXAS REGISTRATION No. 6033 JARDINE@MILLERSURVEY.COM



PROPERTY ADDRESSES: DENNIS ST., HOUSTON, TX 77004 McGOWEN AVE., HOUSTON, TX 77004

LAND TITLE SURVEY 0.2274 ACRE TRACT

AND 0.1371 ACRE TRACT

LOCATED IN THE LUKE MOORE SURVEY, A-51 HARRIS COUNTY, TEXAS



www.millersurvey.com 1760 WEST SAM HOUSTON PARKWAY NORTH ★ HOUSTON, TEXAS 77043 PHONE 713-413-1900 * FAX 713-413-1944 TEXAS FIRM REGISTRATION NO. 10047100

JOB NO.: 3095-JR-PICTURE DWG. NO.: 3095-JR-PICTURE.DWG DRAWN BY: DKA CHK BY: CJQ

SCALE: 1"= 40' DATE: 08/28/2020 | FIELD BOOK: HM M&B Nos. 201250 & 201251

<u>APPROVAL</u> RIGHT OF WAY SECTION SURVEY SECTION KEY MAP No. 494 W GIMS MAP No. 5456 D PARCEL No. JOB No. WBS No.

ILMS No.



